

Asbestos Test Summary Sheet

Site ID	3202.00	Street	21 Baxter Street, Fortitude Valley
Facility	Queensland Teachers Union Health Complex		
Building	21 Baxter Street, Fortitude Valley		

Envirohealth Consulting Pty Ltd a.c.n 054-748-819
 137 Fortescue St Spring Hill, Qld 4000
 Manager Craig Carlson B.Sc

Item Number	Location /Area	Room /Floor	Material /Product	Application /use	Physical Condition	Asbestos Type	Sealed (Yes/No)	Quantity M2	Action Recommend	Photo (Yes/No)	Additional Comments
1	Level 1	External Structural Columns	sheeting	Formwork tube for column	stable	CH	yes		Label & Monitor		Asbestos Register
2	Level 2	External Structural Columns	sheeting	Formwork tube for column	stable	CH	yes		Label & Monitor		Asbestos Register

Abbreviation for Asbestos Types

- CH = Chrysotile Asbestos
- A = Amosite Asbestos
- C = Crocidolite Asbestos
- AT = Actinolite
- T = Tremolite
- NAD = No Asbestos Detected

Further Comments

Laboratory Asbestos Identification Methodology

Microscope Examination using Stereo Microscopy and Polarised Light Microscopy

Asbestos Test Summary Sheet

Site ID	3202.00	Street	25 Baxter Street, Fortitude Valley
Facility	Queensland Teachers Union Health Complex		
Building	25 Baxter Street, Fortitude Valley		

Envirohealth Consulting Pty Ltd a.c.n 054-748-819
 137 Fortescue St Spring Hill, Qld 4000
 Manager Craig Carlson B.Sc

Item Number	Location /Area	Room /Floor	Material /Product	Application /use	Physical Condition	Asbestos Type	Sealed (Yes/No)	Quantity M2	Action Recommend	Photo (Yes/No)	Additional Comments
1	Level 1	External Structural Columns	sheeting	Formwork tube for column	stable	CH	yes		Label & Monitor		Asbestos Register
2	Level 2	External Structural Columns	sheeting	Formwork tube for column	stable	CH	yes		Label & Monitor		Asbestos Register
3	Level @ 2 - 6-11-14	Mail room ceiling	sheeting	Suspect formwork for concrete sill	stable	CH	?				Asbestos Register

Abbreviation for Asbestos Types

- CH = Chrysotile Asbestos
- A = Amosite Asbestos
- C = Crocidolite Asbestos
- AT = Actinolite
- T = Tremolite
- NAD = No Asbestos Detected

Further Comments

Laboratory Asbestos Identification Methodology

Microscope Examination using Stereo Microscopy and Polarised Light Microscopy

